



31. electrical office - top of fluorescent light fixture after sampling - location of sample #5

**SBS Building**  
fka National Old Line Insurance Building





32. G Floor Meeting Rm - Location of sample #1 - top of filuorescent light fixture



33. G Floor Meeting Rm - View of delaminated fireproofing above suspended ceiling



34. B Floor West Mech Rm - View of large chunks of delaminated fireproofing debris on top of suspended ceiling